Monitoring Data Record

Project Title: R-3415 NC 67 Widening COE Action ID: 200520314 Stream Name: UT Lineberry Creek (Site 1) DWQ Number: 05-0061
City, County and other Location Information: NC 67 4.4 miles west of Boonville and just west of
Raccoon Run Road (Sta. 81+00 –L- RT.); Yadkin county
Date Construction Completed: Streambank repairs completed in June 2010 and final planting
completed in January 2011. Monitoring Year: (1) of 3
Ecoregion: 8 digit HUC unit <u>03040101</u>
USGS Quad Name and Coordinates: <u>N 36 14' 39", W 80 47' 7"</u>
Rosgen Classification:
Length of Project: 325 feet Urban or Rural: Rural Watershed Size:
Monitoring DATA collected by: J. Young and J. Lancaster Date: 8/16/11
Applicant Information:
Name: NCDOT Roadside Environmental Unit
Address: 1425 Rock Quarry Road Raleigh, NC 27610
Telephone Number: (919) 861-3772 Email address: mlgreen@ncdot.gov
Consultant Information:
Name:
Address:
Telephone Number: Email address:
Project Status: Complete
Monitoring Level required by COE and DWQ (404 permit/401 Cert.): Level 1 Permit states: The permittee shall visually monitor the vegetative plantings to assess an ensure complete stabilization of the mitigation stream segments. The monitoring shall be conducted annually for a minimum of 3 years after final planting. Photo documentation should be utilized to document the success of the riparian vegetation and submitted to DWC in a final report. After 2 years a site visit shall be conducted by DWC to "close out" the
in a final report. After 3 years a site visit shall be conducted by DWQ to "close out" th mitigation site.
Section 1. PHOTO REFERENCE SITES (Monitoring at all levels must complete this section) Total number of reference photo locations at this site: 4 photos were taken from 2 photopoint locations along the channel and 1 overview photo was taken from the top of the fill slope
Section 1. PHOTO REFERENCE SITES (Monitoring at all levels must complete this section) Total number of reference photo locations at this site: 4 photos were taken from 2 photopoint locations along the channel and 1 overview photo was taken from the top of the file
Section 1. PHOTO REFERENCE SITES (Monitoring at all levels must complete this section) Total number of reference photo locations at this site: 4 photos were taken from 2 photopoint locations along the channel and 1 overview photo was taken from the top of the fill slope
Section 1. PHOTO REFERENCE SITES (Monitoring at all levels must complete this section) Total number of reference photo locations at this site: 4 photos were taken from 2 photo point locations along the channel and 1 overview photo was taken from the top of the fil slope Dates reference photos have been taken at this site: 8/16/11

Section 2. PLANT SURVIVAL Attach plan sheet indicating reference photos. Identify specific problem areas (missing, stressed, damaged or dead plantings): Estimated causes, and proposed/required remedial action: ADDITIONAL COMMENTS: Planted vegetation noted surviving onsite included black willow, silky dogwood, tulip poplar, sycamore, and river birch. Other vegetation noted onsite included fennel, briars, goldenrod, and various grasses.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. <u>Physical measurements of channel stability/morphology will not be required.</u> Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

UT Lineberry Creek (Site 1) is stable for the Year 1 monitoring evaluation.	NCDOT will continue to monitor this
stream relocation.	

Date	Station	Station	Station	Station	Station
Inspected	Number	Number	Number	Number	Number
Structure					
Type					
Is water					
piping					
through or					
around					
structure?					
Head cut or					
down cut					
present?					
Bank or scour					
erosion					
present?					
Other					
problems					
noted?					

Section 4. <u>DEBIT LEDGER</u>

The entire UT to Lineberry Creek (Site 1) stream mitigation site was used for the R-3415 project to compensate for unavoidable stream impacts.

UT LINEBERRY CREEK (SITE 1)



PP#1 Upstream



PP#2 Upstream



Overview Photo



PP#1 Downstream



PP#2 Downstream

